

Found monument spike 0.1 feet below asphalt surface of city street at the position of the corner. This corner was re-set previously from ties of an earlier survey after being disturbed by utility excavation.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THE CORNER

Referenced as shown.

STATE PLANE COORDINATE DATA

CERTIFICATION

I <u>erry</u> O. <u>Allred</u>, Registered Land Surveyor, State of Utah, hereby certify that I have performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve same.

Date 16 Jan 1989

Signature of Surveyor

3817 Reg. No.